

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



Location Entrance – Photo #07203



NW Corner of Location – Photo #07205

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



SE Corner of Location – Photo #07204



Wellheads – Photo #07206

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



Separators – Photo #07208



Tank Battery – Photo #07213




Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



Battery Sign Weathered and Needs Replaced – Photo #07209



Methanol Tank Capacity Not Posted – Photo #07211

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



Unsecured Hatch on Separator – Photo #07210



Open-Ended Load Line – Photo #07214

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



Wildlife Protective Netting Needs Repair – Photo #07212



Lack of Stabilization – Photo #07216

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/4SESW

Location ID: 334843

Date: 10/30/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #07217**



Insufficient Erosion Controls on Lease Road – Photo #07218