

Logos Ignacio 33-8 5: Location ID/API #:067-05476



Photo #1 View of the posted well location signage.

Logos Ignacio 33-8 5: Location ID/API #:067-05476



Logos Ignacio 33-8 5: Location ID/API #:067-05476



Photo #3 Overview of the well location, west side.

Logos Ignacio 33-8 5: Location ID/API #:067-05476



Photo #4 View of the separation equipment.



Logos Ignacio 33-8 5: Location ID/API #:067-05476



Photo #5 View of the wellhead assembly.

Logos Ignacio 33-8 5: Location ID/API #:067-05476



Photo #6 View of unmarked guy anchor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Logos Ignacio 33-8 5: Location ID/API #:067-05476



Photo #7 View of gulley erosion on east side of location.