

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Photo # 4507 From entrance to location



Photo # 4508 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Oct 27, 2023 at 11:19:35 AM
CO



Oct 27, 2023 at 11:20:45 AM
CO

Photo # 4509 Location

Photo # 4510 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Photo # 4511 Location



Photo # 4512 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Photo # 4513 Location



Photo # 4514 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Photo # 4515 Unused equipment/ECD is disconnected



Photo # 4516 Unused equipment/ECD is disconnected

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Photo # 4517 Multiple tank labels are weathered & fading



Photo # 4518 Last Dance 43C wellhead sign weathered & some info illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 43C-3 Pad

Location ID: 334990



Photo # 4519 Debris



Photo # 4520 Debris