



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	new		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation		
Corrective Action:	Comply with Rule 606	Date:	09/25/2023

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	OTHER		
Comment:	electrical disconnect panel, metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	wire		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Ancillary equipment	# 1		
Comment:	electrical disconnect panel		
Corrective Action:		Date:	
Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 239790 Type: WELL API Number: 123-07578 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: at time of inspection well appeared to be shut in

Corrective Action:  Date:

**BradenHead**

Date of Last Brhd Test: 03/01/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Tuesday 11-1-2023 at approximately 14:00, I, Inspector Michael Kester, conducted an on-site reinspection as per Doc #713300044.                      Location: Dorris Ackerson Unit 1                      Operator: KPK                      API#: 123-07578                      County: Weld                      While there, I observed well site with pumping unit.                      At time of inspection there's new wellhead sign complying with doc # 713300044, but weeds have not been addressed.                      Weeds, site, Rule 606, corrective action date 9-25-2023 photo 1, 2, &amp; 3                      Weather conditions: sunny and frozen                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC                      This is a continuing education inspection</p>	kesterm	11/01/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300264	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306048</a>