

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/01/2023

Submitted Date:

11/01/2023

Document Number:

699107719

FIELD INSPECTION FORM
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 Burns, Adam 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD State: CO Zip: 80111

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Harding, Don		don@bm.services	
Leonard, Mike		mike.leonard@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	
Martin, Dene	303-483-3639	DMartin@fundareresources.com	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444251	GAS PROCESSING PLANT	AC			-	REDTAIL GAS PLANT	AC

General Comment:

Inspection due to Incident.

Inspected Facilities

Facility ID: 444251 Type: GAS API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: Active Gas Plant

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 11/1/23 at approximately 1042hrs I, Inspector Adam Burns, Conducted an on-site inspection due to an incident at Redtail Gas a Plant of Fundare Resources Operating Company LLC. Location ID #444251 in Weld County, Colorado. I spoke to Don Harding with Burnt Mountain Services LLC and he informed me that the incident took place in the equipment storage area at the Redtail gas plant. Don informed me that the 3 man crew was heating a valve up on the portable vac trailer. Don informed me that while heating the valve to un-thaw it ignited the gas vapor within the vac trailer. This then caused the pressure to explode causing the back door hatch to be released from the locks, causing the door to hit three crew members. One crew member was hit in the shoulder possibly causing it to be dis-located, this crew member was transported by ambulance to Greeley. The second crew member was lacerated in the abdomen by the cam coupling lock and had 3rd degree burns he was transported by flight for life to Denver. The third crew member had a possible concussion and was transported to Greeley for evaluation. There was no damage to other equipment on location. A spill was released from the vac trailer due to the incident. The spill appears to be approximately 140ft in length, approximately 32ft wide near the vac trailer, and approximately 3ft across at the end of the spill. Dene Martin-Production Superintendent & Bryan Brown-VP Operations were on location with Fundare Resources Company LLC. Sheriff Case ID #23W007054 This is a summary of the inspection report.</p>	burnsa	11/01/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107720	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306275