

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403386824

Date Received:
04/27/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 10 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>cogcc.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 698100287
Inspection Date: 04/18/2023 FIR Submit Date: 04/19/2023 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335359

Location Name: KELL-66S93W Number: 35NENW County: _____
Qtrqtr: NENW Sec: 35 Twp: 6S Range: 93W Meridian: 6
Latitude: 39.487970 Longitude: -107.745300

FACILITY - API Number: 05-045-00 Facility ID: 335359

Facility Name: KELL-66S93W Number: 35NENW
Qtrqtr: NENW Sec: 35 Twp: 6S Range: 93W Meridian: 6
Latitude: 39.487970 Longitude: -107.745300

CORRECTIVE ACTIONS:

1 CA# 169759

Corrective Action: Remove and properly dispose of impacted fluids and oily waste. Comply with Rule 912.a.(2) and submit documentation of cleanup efforts on an FIRR per Rule 912.a.(5). Date: 05/19/2023

Response: CA COMPLETED Date of Completion: 04/22/2023

Operator Comment: The snowmelt was recovered from the lined secondary containment and the algae will die off as the rocks dry out. No spill has occurred. Stained rock has been addressed

COGCC Decision: Approved

COGCC
Representative:

3 CA# 169761

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Remove and properly dispose of oily waste.

Date: 05/19/2023

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator Comment: Stained gravel removed per rules; equipment was inspected and found to be in proper functioning condition.

COGCC Decision: Approved

COGCC
Representative:

5 CA# 169763

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Remove and properly dispose of impacted waste.

Date: 05/19/2023

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator Comment: Stained gravel removed per rules, equipment found to be properly functioning.

COGCC Decision: Approved

COGCC
Representative:

6 CA# 169764

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 05/19/2023

Response: CA COMPLETED

Date of Completion: 04/22/2023

Operator Comment: Stained gravel was removed and disposed of per rules. Equipment has been inspected and is in properly functioning.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 4/27/2023 1:49:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403386824	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files