

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2023

Submitted Date:

10/27/2023

Document Number:

694100201

**FIELD INSPECTION FORM**Loc ID 323149 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		COGCC@KPK.com	<a href="#">All Inspections</a>
Teter, Roy		cogcc@kpk.com	<a href="#">All Inspections</a>
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**General Comment:**

This is an environmental inspection for Location ID 323149 Champlin 86 Amoco. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Orange construction fencing around large open excavation is falling down. Needs to be repaired.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C		Date: 11/10/2023

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
This location is currently a part of a complaint. It has a large open excavation with construction fence surrounding it. It is approximately half full with groundwater. There appears to be an open remediation project ongoing at this location to the SW of the excavation. Possibly SVE/AS. See attached photos.	robinsotl	10/27/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100202	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306840">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306840</a>