

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403581663

Date Received:

11/02/2023

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 701103792

Inspection Date: 08/03/2023

FIR Submit Date: 08/07/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 334273

Location Name: DIVIDE CREEK-68S91W Number: 22NENW County: MESA

Qtrqtr: NENW Sec: 22 Twp: 8S Range: 91W Meridian: 6

Latitude: 39.351150 Longitude: -107.541120

#### FACILITY - API Number: 05-077-00 Facility ID: 221363

Facility Name: DIVIDE CREEK Number: 9

Qtrqtr: NENW Sec: 22 Twp: 8S Range: 91W Meridian: 6

Latitude: 39.351150 Longitude: -107.541120

### CORRECTIVE ACTIONS:

1 CA# 178277

Corrective Action:

Date: \_\_\_\_\_

Document information outlined below on the CA section of COGCC supplemental form 19 spill report to include the following (compliance of COGCC series 1100 flowline rules):

- 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/Operator Determination)
- 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control/ 1104.Integrity Management)
- 3) Description of flowline repair work completed (1102.j. Repair)
- 4) Confirm integrity of flowline repairs/ reconnections (via pressure testing) prior to returning flowline to service (1102.j.4 and 1102.O)
- 5) Ensure flowline(s) are isolated and depressurized; associated wells and isolation valves are SI/ OOSLAT to prevent unintentional release per 1102.j.7 (prior to and time of repair).
- 6) Any historical/ out of service flowlines exposed in the excavation must be abandoned per COGCC rule 1105 (ends sealed per 1105.e.4).

Response: CA COMPLETED

Date of Completion: 11/01/2023

Operator  
Comment:

This was completed with Form 19 doc # 403568427.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 11/2/2023 9:54:05 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files