


Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834



Energy & Carbon Management Commission
40.35609, -104.86131, 1471.5m, 151°
11/02/2023 09:54:04

Production facility



Energy & Carbon Management Commission
40.31432, -104.81135, 57°
11/02/2023 09:46:36

Wellhead sign

Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834



Energy & Carbon Management Commission
40.35569, -104.86124, 1480.0m, 239°
11/02/2023 09:57:13

Valve leak



Energy & Carbon Management Commission
40.35569, -104.86124, 1479.4m, 227°
11/02/2023 09:57:23

Valve leak

Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834



Valve leak



Valve leak

Inspection Photos
Location Name: HSR Stroh 11-35
Location ID: 326834



Check valve leak



Valve leak