

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2023

Submitted Date:

11/01/2023

Document Number:

710500082

FIELD INSPECTION FORM

Loc ID 333760 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159087	UIC DISPOSAL	AC	10/11/2002		-	CIMARRON 32-18 WD (EPA)	EI
262549	WELL	IJ	12/03/2014	DSPW	071-07565	CIMARRON 32-18 WD	EI
333760	LOCATION	AC			-	CIMARRON-632S67W 18SWNE	EI
414705	PIT	AC			-	CIMARRON 32-18 WD EMERGENCY	EI

General Comment:

[This is an Environmental Inspection for the Cimarron 32-18 WD; Location ID 333760, Located in Las Animas County, Co](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: There is a tank located on the location, tank appears to have oil stained gravel in the secondary containment

Corrective Action: Cleanup Stained Material, Repair and Maintain Equipment per Rule 608.e

Date: 12/06/2023

Type

OTHER

Comment: Stained Soil Observed in Generator Building

Corrective Action: Cleanup affected soil and maintain equipment per Rule 608.e.

Date: 12/06/2023

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 159087 Type: UIC API Number: - Status: AC Insp. Status: EI

Facility ID: 262549 Type: WELL API Number: 071-07565 Status: IJ Insp. Status: EI

Facility ID: 333760 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 414705 Type: PIT API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Emergency Lined: YES Pit ID: 414705 Lat: 37.258996 Long: -104.925186

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: PVC Liner Condition: Adequate

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	414705	1841362	

Monitoring:	Monitoring Type	Comment
	Chain	Chain Present

COGCC Comments

Comment	User	Date
There is a tank located on the location, tank appears to have oil stained gravel in the secondary containment Cleanup Stained Material, Repair and Maintain Equipment per Rule 608.e	sanchezcc	11/02/2023
Rig Anchors not properly marked. mark Rig Anchors per Rule 603.j	sanchezcc	11/02/2023
Cleanup affected soil and maintain equipment per Rule 608.e	sanchezcc	11/01/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500098	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307048