

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2023

Submitted Date:

11/02/2023

Document Number:

705000500

FIELD INSPECTION FORM

Loc ID 331207 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Oxy		ECMCInspections@oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259370	WELL	SI	12/01/2020	GW	123-20312	COYLE 13-18A	PA
331207	LOCATION	AC			-	COYLE-62N66W 18SWSW	EG

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 259370 Type: WELL API Number: 123-20312 Status: SI Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Well is plugged and abandoned (Coyle 13-18A); ECMC form 42 notice of start of plugging operations doc #403469349 received on 07/19/2023. The OLF wellhead flowline has been AIP/ riser removed. The facility/ tank battery has been decommissioned; tanks and equipment removed. On location flowlines have been removed; ECMC form 42 notice of flowline abandonment completed doc #403561141 received 10/16/2023. No flowlines/ risers observed. Fenced excavation observed at PA well area. Excavation/ remediation work is in progress.

Corrective Action:

Date:

Facility ID: 331207 Type: LOCATION API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #403569770 received on 10/26/2023: On October 23, 2023, historically impacted soil was discovered following cut and cap operations at the Coyle 13-18A flowline location. Excavation and assessment activities are ongoing. Site infrastructure has been removed and will not be replaced.	maclarej	11/02/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
705000501	Signage at soils stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307553
705000502	Fenced excavation at PA well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307554