

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/11/2023

Submitted Date:

11/02/2023

Document Number:

701103841

FIELD INSPECTION FORMLoc ID 322372 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 51130

Name of Operator: LOCIN OIL CORPORATION

Address: 600 TRAVIS ST STE 6161

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Benedict, Daniel	(303) 902-1593	dbenedict@locin.energy	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210380	WELL	SI	06/01/2020	GW	045-06136	FEDERAL 22-9	EG

General Comment:

Flowline integrity inspection

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	2- unused 2" risers on location.		
Corrective Action:	Comply with Rule 606 Immediately within 24 hours comply with OOSLAT requirements per Rule 1101.a.(3).C. (isolate and tag)	Date:	12/05/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210380 Type: WELL API Number: 045-06136 Status: SI Insp. Status: EG**Flowline**

#1	Type:	2 of Lines
----	-------	------------

Flowline Description

Flowline Type: Size: 2" Material: Carbon Steel
Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 2 Unused flowline risers.

Corrective Action: Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103849	Flowline integrity inspection 701103841 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307665