



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type			
Comment:	<a href="#">See Inspection Doc # 702402455 for related shared facilities and equipment</a>		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	<a href="#">AG panel</a>		
Corrective Action:		Date:	
Type			
Comment:	<a href="#">See Inspection Doc # 702402455 for related shared facilities and equipment</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	<a href="#">See Inspection Doc # 702402455 for related shared facilities and equipment</a>		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	<a href="#">appears plumbed to surface</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">automation</a>		
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:		<a href="#">See Inspection Doc # 702402455 for related shared facilities and equipment</a>			
Corrective Action:				Date:	
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 263126 Type: WELL API Number: 123-20838 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On Thursday 11-2-2023 at approximately 1530 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: Civitas/Crestone Peak Resources                      Location name: Townsend 62N67W 5SWSE                      Location ID # 331525                      Well Name: Townsend 34-5                      API # 05-123-20838                      County: Weld                      Weather: Clear, Sunny.                      Location: Dry.                      While there, I observed a Wellsite, PR at the time of the inspection.                      During this inspection, I observed no compliance issues:                      See attached photos.                      No follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	11/02/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402462	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307955">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307955</a>