

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/01/2023

Submitted Date:

11/02/2023

Document Number:

707602011

**FIELD INSPECTION FORM**

Loc ID: 447718      Inspector Name: Evins, Bret      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
 Name of Operator: NOBLE ENERGY INC  
 Address: 2001 16TH STREET SUITE 900  
 City: DENVER      State: CO      Zip: 80202

**Findings:**

13      Number of Comments  
 0      Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447717	TANK BATTERY	AC	09/12/2016		-	SCHMIER-65N64W 32NWNW	IO

**General Comment:**

This is a TANK BATTERY inspection.  
 Associated Well(s): 3: Temporarily Abandoned | TA.  
 Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (336634, 302380).  
 (Well(s): 3: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

Centralized Battery formerly served 2 Location IDs (305730, 327645).  
 (Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (447717).  
 (Battery: Inactive | Shut-down).

Reference:  
 Fwp-F.) Follow-up to Field Inspection Report doc. #707601839 dated 09/13/2023.  
 A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2).  
 B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1).  
 C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1).  
 D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1).  
 E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1).  
 F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.

Location			
<b>Lease Road:</b>			
	Type Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type BATTERY		
Comment:	<p>Prior insp: Sign w/ Emergency number, Company, &amp; Well names NOT posted at Battery site. Refer to Rule 605.e for guidance. *Post sign w/ Emergency number, Company &amp; Well names at Battery site. Comply with Rule 605.e. Corrective Action date: 10/16/2023. (30-days). See photo #1.</p> <p>This insp: **Sign(s) w/ Emergency number, Company &amp; Well names NOW posted at Battery site. as of 11/01/2023. See photo(s) #1, 4, 5, 6. Corrective Action(s), NOW resolved.</p> <p>CECMC provided photo(s) for verification.</p>		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	<p>Prior insp: Sign w/ Emergency number, Company, &amp; Well names NOT posted at Battery site. Refer to Rule 605.e for guidance. *Post sign w/ Emergency number, Company &amp; Well names at Battery site. Comply with Rule 605.e. Corrective Action date: 10/16/2023. (30-days). See photo #1.</p> <p>This insp: **Sign(s) w/ Emergency number, Company &amp; Well names NOW posted at Battery site. as of 11/01/2023. See photo(s) #1, 4, 5, 6. Corrective Action(s), NOW resolved.</p> <p>CECMC provided photo(s) for verification.</p>		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF. Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF. Shut-down.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas Sales. Calibration card(s) indicates calibration > 1 year. Last calibration: 03/25/2020. Inactive. NO production.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned   TA). Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive   Shut-down).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

<b>Paint</b>	
Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		40.359546,-104.582714
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Berms shared w/ crude oil, produced H2O tank(s).				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 447717 Type: TANK API Number: - Status: AC Insp. Status: IO

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
---------	------	------

<p><b>CECMC Inspection Report Summary:</b></p> <p>On WED 11/01/2023 at approximately 14:38 hrs. I, Bret Evins, conducted an onsite inspection at:                  Operator Name: NOBLE ENERGY INC                  Facility Name: SCHMIER-65N64W/32NWNW                  Facility ID: 447717                  Location Name: SCHMIER-65N64W/32NWNW                  Location ID: 336634                  Associated Well Name(s): 3: Temporarily Abandoned   TA.                  Schmier B 32-30D, Schmier B 32-31D, Schmier B 32-32.                  API:                  123-29003, 123-29659, 123-29039.                  Location County: Weld County, Colorado                  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                  Associated Well(s): 3: Temporarily Abandoned   TA.                  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (336634, 302380).                  (Well(s): 3: Temporarily Abandoned   TA ; 1: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery formerly served 2 Location IDs (305730, 327645).                  (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (447717).                  (Battery: Inactive   Shut-down).</p> <p>Reference:                  Fwp-F.) Follow-up to Field Inspection Report doc. #707601839 dated 09/13/2023.                  A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2).                  B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1).                  C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1).                  D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1).                  E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1).                  F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following prior possible compliance issue(s) appear to be addressed:                  1.) Sign w/ Emergency number, Company, &amp; Well names NOT posted at Battery site. Refer to Rule 605.e for guidance.                  *Post sign w/ Emergency number, Company &amp; Well names at Battery site. Comply with Rule 605.e.                  Corrective Action date: 10/16/2023. (30-days).                  **Sign(s) w/ Emergency number, Company &amp; Well names NOW posted at Battery site. as of 11/01/2023.                  See photo(s) #1, 4, 5, 6.                  Corrective Action(s), NOW resolved.</p> <p>CECMC provided photo(s) for verification.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	<p>evinsb</p>	<p>11/02/2023</p>
---	---------------	-------------------

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602012	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307961</a>