

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2023

Submitted Date:

11/02/2023

Document Number:

701007596

FIELD INSPECTION FORMLoc ID 314190 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|-----------------------------|---------|
| Strachan, Steve | (303) 785-7006 | sms@strachanexploration.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 227865 | WELL | SI | 02/01/2023 | GW | 099-06191 | STATE 4-8 | SI |

General Comment:

Routine Inspection

Location

| | | | |
|--------------------|------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel trail through pasture | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Stickers on tank | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to unit | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------|--|--|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | Date: | | |

Overall Good: ☒

| | | | | |
|--|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | |
|--------------------|--------------------------------|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Wire fence around tank battery | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|-------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Gas scrubber | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Kohler gas engine | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | Sentry unit | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|----------------|---|----------|-----------|---------|-----------------------|--|
| PRODUCED WATER | 0 | 300 BBLS | STEEL AST | | 38.150740,-102.150740 | |

| | | | | | | | |
|--------------------|----------|--|---------------------|-------------|-----------------------|-------|--|
| Comment: | | Steel water tank removed from location | | | | | |
| Corrective Action: | | | | | | Date: | |
| <u>Paint</u> | | | | | | | |
| Condition | | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |
| <u>Berms</u> | | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| CRUDE OIL | 0 | 300 BBLs | STEEL AST | | 38.150740,-102.150740 | | |
| Comment: | | Steel oil tanks removed from location | | | | | |
| Corrective Action: | | | | | | Date: | |
| <u>Paint</u> | | | | | | | |
| Condition | | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |
| <u>Berms</u> | | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| PRODUCED WATER | 1 | 200 BBLs | FIBERGLASS AST | | 38.150860,-102.492750 | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| <u>Paint</u> | | | | | | | |
| Condition | | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |
| <u>Berms</u> | | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 227865 | Type: | WELL | API Number: | 099-06191 | Status: | SI | Insp. Status: | SI |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Meter run for (State 4-8) 3685' E of location @ 38.15074/-102.48007 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------|---|
| 701007610 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308034 |
| 701007611 | Old Tank battery site | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308035 |