

**Inspection Photos 11/1/23**  
**Location Name: Dent 1-16**  
**API: 05-099-06211**



Brian Welsh SE Field Inspector COGCC  
38-13447-102-98237-3549-70  
11/01/2023 13:05:25

**Prime mover and ancillary equipment**



Brian Welsh SE Field Inspector COGCC  
38-13447-102-98237-3549-70  
11/01/2023 13:05:10

**Location photo of unit and tanks**



**Inspection Photos 11/1/23**  
**Location Name: Dent 1-16**  
**API: 05-099-06211**



Brian Welsh SE Field Inspector COGCC  
38.13458, -102.58248, 3640.3ft  
11/01/2023 13:06:41

**Bridle still connected to polished rod and downhole equipment in wellbore**



Brian Welsh SE Field Inspector COGCC  
38.13458, -102.58256, 3636.0ft  
11/01/2023 13:06:52

**South side of tank battery looking north**



Inspection Photos 11/1/23  
Location Name: Dent 1-16  
API: 05-099-06211



Southwest corner of tank battery



Northwest corner of tank battery



Inspection Photos 11/1/23  
Location Name: Dent 1-16  
API: 05-099-06211



Northeast corner of tank battery



West side of tanks looking east

**Inspection Photos 11/1/23**

**Location Name: Dent 1-16**

**API: 05-099-06211**



**Active water leak found at time of inspection. Notified OWP manager. Water seems to be high H<sub>2</sub>S content**

