

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2023

Submitted Date:

11/02/2023

Document Number:

708902106

FIELD INSPECTION FORM

Loc ID 335341 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257429	WELL	PR	09/21/2000	GW	045-07561	CLOUGH RMV 218-21	PR
271029	WELL	PR	06/29/2004	GW	045-09833	CLOUGH RWF 414-21	PR
271073	WELL	PR	07/01/2004	GW	045-09834	CLOUGH RWF 514-21	PR

General Comment:

[CECMC Inspection Report Summary](#)
On 11/02/2023 at approximately 11:49 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC CLOUGH RMV 218-21 pad. Location # 335341 in Garfield County Colorado.
Please refer to inspection 708900256 conducted on 04/10/2023, previous corrective actions have been completed.
Location is within High Priority/Density Habitat areas & in close proximity to a Bald Eagle Roost site.
Location is approximately 30-40 yards from 2 creeks/drainages that both contribute to the Colorado River.
While there, I observed normal production operations.

This is a summary of inspection report.

Remote location/split pad - Wellheads only, production tanks & separators located on the CLOUGH RMV 32-21 pad, location # 323916

Location

Lease Road:			
	Type Access		
comment:	Access road to location has a small creek running through it aproximately 40 yards from entrance to location. The road has started to erode where creek intersects the access road but was still passable at time of inspection.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
	Type BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
	Type WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 8		
Comment:	Marked		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Taylor plugs located on all bradenhead, all bradenhead valves are accessible.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: <u>257429</u>	Type: <u>WELL</u>	API Number: <u>045-07561</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>271029</u>	Type: <u>WELL</u>	API Number: <u>045-09833</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>271073</u>	Type: <u>WELL</u>	API Number: <u>045-09834</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	<u>Producing, well on plunger lift</u>		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small areas of light compaction
		Ditches				
		Compaction				
		Gravel				Sparse to none in some sections
Gravel						Sparse to none in some areas
		Culverts				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Remote location/split pad - Wellheads only, production tanks & separators located on the CLOUGH RMV 32-21 pad, location # 323916	smelserw	11/02/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902107	Inspection 708902106 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308150
708902108	Inspection 708902106 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308151