

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

712700826**FIELD INSPECTION FORM**Loc ID 306839 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269226	WELL	PR	05/01/2023	CBM	067-08868	BROWN 32-6-10 2	PR

**General Comment:**SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Access from CR 988, private road.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Contents and volume label, NFPA placard on produced water tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Metal sign posted at location entrance.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Warning signs on pumpjack, NFPA placards on separator and meterhouse.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	SEPARATOR			
Comment:	Cattle panel around separator, tank, meterhouse, and telemetry.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panel around wellhead and pumpjack.			
Corrective Action:				Date:
<b>Equipment:</b>				
			corrective date	
Type: Ancillary equipment	# 2			
Comment:	Cathodic protection, electrical control box.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On separator vent stack.			
Corrective Action:				Date:

Type: Deadman # & Marked	# 4	
Comment:	4 unmarked guy anchors. See photo #8.	
Corrective Action:	Adequately mark guy anchors according to Rule 1003, if anchor is no longer serviceable it should be removed as unused equipment.	Date: 11/17/2023
Type: Prime Mover	# 1	
Comment:	Electric motor	
Corrective Action:		Date:
Type: Flow Line	# 2	
Comment:	3" line from wellhead to separator. 1" line from separator to wellhead.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Telemetry	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Wellhead	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	PVC access	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	3" line from separator to meterhouse. Calibration date 1/9/2023.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.035480,-107.485030
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	269226	Type:	WELL	API Number:	067-08868	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	01/13/2023	Annual Brhd Completed?	Yes						
Last Brhd Test Results	Initial Surf Csg Pressure:	0	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass					
Ditches	Pass					
Sediment Traps	Pass	Gravel	Pass			
Berms	Pass	Culverts	Pass			
Rip Rap	Pass	Ditches	Pass			

Comment: [No visible erosion or sediment migration observed during inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700834	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308761">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308761</a>