

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2023

Submitted Date:

11/03/2023

Document Number:

712700825

FIELD INSPECTION FORM

Loc ID 326189 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216015	WELL	PR	04/14/2003	CBM	067-07621	BROWN 32-6-10 1	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Access from CR 988, private road.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Warning signs, NFPA placards on separator and meterhouse. Warning signs on electrical equipment.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal sign posted at location entrance.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	24 hour operator contact number and 911 local emergency number posted on well location signage.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Cattle panel around buried valve cans.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panel around wellhead/pumpjack and control box.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe rail around cathodic protection.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Cattle panel around telemetry.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panel around separator and meterhouse.		
Corrective Action:		Date:	
Type	OTHER		

Comment:	Cattle panel around electrical service boxes.			
Corrective Action:			Date:	
Equipment:				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gathering Line	# 2			
Comment:	Two buried valve cans. Pipeline ROW adjacent to location.			
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead			
Corrective Action:			Date:	
Type: Ancillary equipment	# 4			
Comment:	Telemetry, Electrical transformer, electrical service, cathodic protection.			
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:	On separator vent stack.			
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	3" line from separator to meterhouse. Calibration date 1/9/2023.			
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	3" line from wellhead to separator.			
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	PVC access			
Corrective Action:			Date:	
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				

Corrective Action:

Date:

Inspected Facilities

Facility ID: 216015 Type: WELL API Number: 067-07621 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/13/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 17 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
Berms	Pass	Ditches	Pass			
Rip Rap	Pass	Culverts	Pass			
Ditches	Pass	Gravel	Pass			

Comment: [Sediment migration onto the location from cut slopes. See photo #8.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700833	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6308759