


TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712



Sign at tank battery




Unused equipment on location

TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712



Debris. Open to wildlife.



Debris

**TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712**



Open end loadline



Condensate tank leaking.

TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712



Bradenhead connected to flowline



Unmarked anchor

TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712



Open to wildlife



Open to wildlife

**TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712**



Debris



Tank disconnected and label illegible

TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712



Damaged rain cap



Damaged rain cap

**TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712**



Location from Northwest corner. Entrance to location.



Location from Southwest corner

**TEP Rocky Mountain LLC
Diamond Elk-67S95W 12NWNW
Location ID: 334712**



Location from Southeast corner



Location from Northeast corner