

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2023

Submitted Date:

11/04/2023

Document Number:

698601224**FIELD INSPECTION FORM**Loc ID 303016 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 252271 | WELL | PR | 02/23/1978 | GW | 125-06141 | BERT L HENDERSON 1 | PR |

General Comment:

Routine Inspection.

Location

| | | | |
|--------------------|---------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign located inside well fencing. | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Well sign at gas meter run shed inside well fencing. | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Content/Quantity/Hazard sign at tank. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Emergency contact information posted on well sign, meter shed sign, and tank sign.

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Stock panel fencing around surface equipment at well site. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | The above ground dump line is rusted/corroded full of holes between separator and produced water tank. There is no evidence of spill or release from the line. Currently the dump valve is closed. As BMP the line should be removed/replaced, disconnected or dump line valve should be locked out and tagged out. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Digital Gas Meter Run. Meter Calibration/Test Log dated 3-13-23. Well Inlet Valve open. Gas Outlet Valve open. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |

| | | | | |
|---------------------------|---|--|-------|--|
| Comment: | Metal Separator Shed. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve open. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Metal Meter Shed. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Bradenhead | # 1 | | | |
| Comment: | Bradenhead plumbed to surface. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Dehydrator | # 1 | | | |
| Comment: | Dehydrator on gas meter run inlet. | | Date: | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 200 BBLS | PBV FIBERGLASS | | , |
| Comment: | Tank does not currently appear to be in use. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 252271 | Type: | WELL | API Number: | 125-06141 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Electronic Well File reflects last Production/Status reported 8/1/2023 and Well Status as PR. Based on current valve settings the well is PR. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 698601259 | Inspection photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6309949 |