

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2023

Submitted Date:

11/04/2023

Document Number:

707602019

FIELD INSPECTION FORMLoc ID 323370 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323370	LOCATION	AC			-	HOLMAN-65N64W 14SWNE	IO

General Comment:

This is a BATTERY inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID
(323370).

(Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery serves 1 Tank Battery Facility ID
(Pending).**Reference:**

Fwp-B.) Follow-up to Field Inspection Report doc. #707601971 dated 10/19/2023.

A.) Field Inspection Report doc. #707601969 and/or Location ID #323370
for TA Well(s) info.B.) Field Inspection Report doc. #707601971 and/or Location ID #323370
for Battery / Facility, Equipment info.

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Prior insp: Overgrown vegetation at produced H2O vault. Refer to Rule 606.c for guidance. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved. *Remove, manage, & control overgrown vegetation around produced H2O vault. Comply with Rule 606.c. Corrective Action date: 11/20/2023. (30-days). See photo #3.</p> <p>This insp: **Overgrown vegetation at produced H2O vault NOW mitigated as of 11/03/2023. See photo(s) #3, 4. Corrective Action(s), NOW resolved. CECMC provided photo(s) for verification.</p>		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Gas Sales: Calibration card(s) indicates calibration > 1 year. Last calibration: 07/22/2014. Inactive, NO production.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location ID (323370). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		40.401416,-104.513819
Comment:	North produced H2O vault, East of separator.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)	24 Bbls.						
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:		Berms shared w/ crude oil tank(s), South produced H2O vault(s).					
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	100 BBLS	STEEL AST		40.399380,-104.514370		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:		Berms shared w/ crude oil tank(s), South produced H2O vault(s).					
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:					Date:		
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:					Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On FRI 11/03/2023 at approximately 15:39 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: HOLMAN-65N64W/14SWNE Location ID: 323370 Well Name(s): Holman 14-1. API: 123-12922. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (323370). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference: Fwp-B.) Follow-up to Field Inspection Report doc. #707601971 dated 10/19/2023. A.) Field Inspection Report doc. #707601969 and/or Location ID #323370 for TA Well(s) info. B.) Field Inspection Report doc. #707601971 and/or Location ID #323370 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following prior possible compliance issue(s) appear to be addressed: 1.) Overgrown vegetation at produced H2O vault. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around produced H2O vault. Comply with Rule 606.c. Corrective Action date: 11/20/2023. (30-days). **Overgrown vegetation at produced H2O vault NOW mitigated as of 11/03/2023. See photo(s) #3, 4. Corrective Action(s), NOW resolved.</p> <p>CECMC provided photo(s) for verification.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	11/04/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707602020	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310022