

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-14B (N9B) Pad

Location #: 334678



Photo # 4929 From entrance to location



Photo # 4930 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-14B (N9B) Pad

Location #: 334678




Photo # 4931 Location



Photo # 4932 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC GMR 9-14B (N9B) Pad
Location #: 334678



Photo # 4933 Location



Photo # 4934 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-14B (N9B) Pad

Location #: 334678



Photo # 4935 Location



Photo # 4936 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-14B (N9B) Pad

Location #: 334678



Photo # 4937 Location



Photo # 4938 Stained gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 9-14B (N9B) Pad

Location #: 334678



Photo # 4939 Stained gravel