

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad

Location #: 334584



Photo # 4857 From entrance to location



Photo # 4858 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad

Location #: 334584




Photo # 4859 Location

Photo # 4860 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad
Location #: 334584



Photo # 4861 Location



Photo # 4862 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad

Location #: 334584



Photo # 4863 Location



Photo # 4864 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad

Location #: 334584



Photo # 4865 Location



Photo # 4866 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad

Location #: 334584



Photo # 4867 Flowline heating insulation open ended



Photo # 4868 Stained gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC HMU 9-5 (E9W) Pad

Location #: 334584



Photo # 4869 Stained gravel