

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2023

Submitted Date:

11/05/2023

Document Number:

698601267**FIELD INSPECTION FORM**Loc ID 303573 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253310	WELL	PR	05/02/1986	GW	125-07187	RUTLEDGE 1	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access.		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Well sign posted at gas meter run.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign located inside well fencing.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Emergency contact information posted on both the Well location and Meter Shed signs.	
Corrective Action:		Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stool panel fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Remote gas meter site stock panel fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Tubing removed from the wellbore. Casing valve open.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Meter Shed at remote Gas Meter Run.		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 46. Digital Gas Meter Run. Meter Calibration/Test Log dated 2-8-23. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	253310	Type:	WELL	API Number:	125-07187	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Electronic Well File reflects last Production/Status reported 8/1/2023 and Well Status as PR. Based on current valve settings the well is PR.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601268	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310459