

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2023

Submitted Date:

11/05/2023

Document Number:

698601236**FIELD INSPECTION FORM**Loc ID 304214 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------|---------|
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 254205 | WELL | PR | 11/09/1998 | GW | 125-08083 | J BROPHY 29-27 | PR |

General Comment:Routine Inspection.

Location

| | | | |
|--------------------|---------------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. | | |
| Corrective ActionL | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Label unreadable. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 12/06/2023 |
| Type | OTHER | | |
| Comment: | Well sign posted at remote separator shed door. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Well sign at well location. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Emergency contact information posted on both the Well location and Meter Shed signs.

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | At remote facility. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Tubing in the wellbore. Tubing valve open. Casing valve not connected. | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | Dehydrator on gas meter run inlet. | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Meter Shed at remote Gas Meter Run. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |

| | | | | |
|---------------------|--|--|-------|--|
| Comment: | Bradenhead plumbed to surface. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Remote Gas Meter Run located on access road. Digital Gas Meter Run. Meter Calibration/Test Log dated 11-20-22. Well Inlet Valve open. Gas Outlet Valve open. | | Date: | |
| Corrective Action: | | | Date: | |
| Type: Other | # 1 | | | |
| Comment: | Separator shed at remote facility. | | Date: | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-------------------|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | | PBV FIBERGLASS | | , |
| Comment: | Label unreadable. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|-------------------|--|
| Condition | Adequate | |
| Other (Content) | Label unreadable. | |
| Other (Capacity) | Label unreadable. | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 254205 | Type: | WELL | API Number: | 125-08083 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Electronic Well File reflects last Production/Status reported 8/1/2023 and Well Status as PR. Based on current valve settings the well is PR. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [No stormwater issues noted at time of inspection.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 698601273 | Inspection photos. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6310566 |