

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2023

Submitted Date:

11/06/2023

Document Number:

690011637

**FIELD INSPECTION FORM**Loc ID 332952 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                   | Comment                         |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy        |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 250163      | WELL | SI     | 03/01/2022  | GW         | 123-17966 | HSR CAROL MILLER 3-31 | TA          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 1 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Tanks and Berms:**

| Contents           | #                               | Capacity | Type                | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|---------------------|---------|--------|
|                    |                                 |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Battery location number: 319447 |          |                     |         |        |
| Corrective Action: |                                 |          |                     |         | Date:  |

**Paint**

|                  |                      |
|------------------|----------------------|
| Condition        | <input type="text"/> |
| Other (Content)  | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |
| Other (Type)     | <input type="text"/> |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 250163 Type: WELL API Number: 123-17966 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well not connected with flow line.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 06/07/2023

Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 18Fluid Type: NoneEnd Surf Csg Pressure: --Comment: Plumbed to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User            | Date              |
|---|-----------------|-------------------|
| <u>routine wellhead inspection</u><br><u>Well tagged "Preabandoned"</u> | <u>carlilec</u> | <u>11/06/2023</u> |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num     | Description  | URL  |
|------------------|--------------|--|
| <u>690011638</u> | <u>Photo</u> | <u><a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6311921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6311921</a></u> |