

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 27-2B1 (B27) Pad

Location #: 335376



Photo # 5394 From entrance to location



Photo # 5395 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 27-2B1 (B27) Pad

Location #: 335376



Photo # 5396 Location



Photo # 5397 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 27-2B1 (B27) Pad

Location #: 335376



Photo # 5398 Location



Photo # 5399 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 27-2B1 (B27) Pad

Location #: 335376



Photo # 5400 Location



Photo # 5401 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 27-2B1 (B27) Pad

Location #: 335376



Photo # 5402 Stained gravel



Photo # 5403 Stained gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 27-2B1 (B27) Pad

Location #: 335376



Photo # 5404 Open ended load line



Photo # 5405 Battery sign lacks required info