

Inspection Photos

10/18/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539

Inspection Doc: 696205405

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 1: Photos 1-2 taken from the west end of the working pad surface. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 3: Wellhead



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 4: Photo shows cuttings trench on the north end of the Location; trench required Form 15 permitting.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



39.4923157N 108.20740709W
November 6, 2023



39.4923174N 108.20739794W
November 6, 2023

Photo 5: Tanks on east end of the Location lacks required labeling/signage.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 6: Photos 6-8 show sediment traps constructed on the east, south and west ends of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



November 6, 2023

Photo 8: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 5: Photos examples showing the stormwater diversion ditch constructed along the Location's perimeter.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 10: Photos 10-12 example showing control measures to stabilize, as well as to minimize erosion and degradation are missing or insufficient along the fill slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 11: See comments under photo 10. Photo also example showing various tarp/liner material observed along the fill slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 12: See comments under photo 11.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 13: Trash/debris on Location

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 14: Photos 14-16 taken from the access road / pipeline right away. Photos show stormwater and erosion control measures to manage runoff to minimize erosion, degradation and sediment transport are missing or insufficient along the access road/ROW.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 15: See comments under photo 14.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



Photo 16: Photo shows pipeline ROW recently constructed. Stormwater and erosion control measures not apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322539



November 6, 2023

Photo 17: Photo shows broken gate remains improperly stored along the O&G access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources