

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/07/2023

Document Number:

713300271**FIELD INSPECTION FORM**Loc ID 317736 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239890	WELL	PR	06/01/2023	OW	123-07678	CARL M CARY 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:		
Type	DEBRIS	
Comment:	DEAD overgrown vegetation, around well head and equipment	
Corrective Action:	Comply with Rule 606	Date: 11/14/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:		
Type	PUMP JACK	
Comment:	Safety Guard panels	
Corrective Action:		Date:

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	electrical motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electrical panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 239890 Type: WELL API Number: 123-07678 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: at time of inspection well appeared to be shut inCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/21/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 11-7-2023 at approximately 12:00, I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Carl M Cary 1</p> <p>Operator: KPK</p> <p>API#: 123-07678</p> <p>County: Weld</p> <p>While there, I observed well site with pumping unit.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Debris, Rule 606, corrective action date 11-14-2023</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC</p> <p>This is a continuing education inspection</p>	kesterm	11/07/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300272	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314386