

**Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094**



**Access to county road**



**Access road from county road**

**Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094**



**Access road to location**



**Entrance to location**

Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094



As signs are replaced additional information will be required

Debris

Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094



Sign at tank battery missing require information



Debris from 6/1/23

Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094



**Fence not maintained**



**Fence not maintained**

**Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094**




**Evaporation pit**



**Evaporation pit**

Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094



Insufficient cap on loadline



Insufficient cap on loadline

**Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094**



**Location from Southwest corner**

**Location from Northwest corner**

**Diversified Energy LLC  
Bingman 1-14  
Location ID: 313094**



**Location from Northeast corner**

**Location from Southeast corner**