

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/07/2023

Document Number:

701007620**FIELD INSPECTION FORM**Loc ID 318187 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Revas, Robbie		robbie.revas@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240815	WELL	PR	08/01/2023	OW	123-08603	MARIE GERHARDT B 4	PR

**General Comment:**[Routine Inspection](#)

**Location****Lease Road:**

Type	Access		
comment:	Access wellhead from residential road		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign laying on the ground by wellhead. Sign is faded and doesn't have all required information		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	12/07/2023

**Emergency Contact Number:**

Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Wire fence around wellhead and concrete pads		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	All deadmen are marked		
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:	Plunger lift has been removed and converted to conventional lift		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead plumbed to surface on south side of wellhead		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	240815	Type:	WELL	API Number:	123-08603	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift has been removed and converted. Polished rod and stuffing box have been installed at time of inspection								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment: [Crushed concrete and asphalt have been added south of wellhead for heavy equipment mobility](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007624	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314574">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314574</a>