

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/07/2023

Document Number:

701007621**FIELD INSPECTION FORM**Loc ID 318318 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
Revas, Robbie		robbie.revas@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241098	WELL	SI	07/01/2023	GW	123-08886	SHELDON R. SICKLER 4	SI

General Comment:[Routine Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:	Trail through farm ground			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign mounted to unit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Dead weeds around ancillary equipment need maintenance			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Wire fence around unit and wellhead			
Corrective Action:				Date:
Type	OTHER			
Comment:	Pipe fence around electric panel and power transformer			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Gas Meter Run	# 0			
Comment:	Meter run moved to Sheldon Sickler 2 inventory			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Lufkin 160			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:	HHS moved to Sheldon Sickler 2 inventory		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Electric panel, electric meter, transformer and phase convertor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	300 BBLs	STEEL AST		40.091950,-104.870680
Comment:	Water tank has been removed from location as of 11/7/23				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0	300 BBLs	CENTRALIZED BATTERY		40.092120,-104.869610
Comment:	Central tank battery for Sheldon Sickler 1,2,3,4 1180' North of wellhead @ 40.092120/-104.869610. Tank is moved to Sheldon Sickler 2 inventory				
Corrective Action:			Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	241098	Type:	WELL	API Number:	123-08886	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	Well is SI at time of inspection. Central tank battery for Sheldon Sickler 1,2,3,4 1180' North of wellhead @ 40.092120/-104.869610								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other				

Comment: [Access is farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701007622	Pumping unit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314575
701007623	Ancillary equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6314576