

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

10/11/2023

Document Number:

403499017

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10575 Contact Person: James Miller
Company Name: 8 NORTH LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmillier@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 461164 Location Type: Production Facilities
Name: DF RANCH-611N61W Number: 22SENW
County: WELD
Qtr Qtr: SENW Section: 22 Township: 11N Range: 61W Meridian: 6
Latitude: 40.906924 Longitude: -104.200678

Description of Corrosion Protection

8 North's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, 8N will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. 8N retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

8 North's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, 8N ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

NA

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461526 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 410131 Location Type: Well Site ☐
Name: DF RANCH-611N61W Number: 22NWSW
County: WELD No Location ID
Qtr Qtr: NWSW Section: 22 Township: 11N Range: 61W Meridian: 6
Latitude: 40.905030 Longitude: -104.198750

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 02/09/2010
Maximum Anticipated Operating Pressure (PSI): 46 Testing PSI: 46
Test Date: 09/30/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 04/18/2019

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The entire 2" steel line was removed. The 1' poly line was unable to be removed and was cut and capped below grade and left in place.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461525 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 302916 Location Type: Well Site ☐
Name: DF RANCH-611N61W Number: 22SEnw
County: WELD No Location ID
Qtr Qtr: SENW Section: 22 Township: 11N Range: 61W Meridian: 6
Latitude: 40.908630 Longitude: -104.194060

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 12/01/2009
Maximum Anticipated Operating Pressure (PSI): 57 Testing PSI: 57
Test Date: 09/18/2018

OFF LOCATION FLOWLINE Out of Service

Date: 05/17/2023

☒ Entire Line Removal☐ Partial Line Removal**Description of Out of Service:**

The flowline (12330024FL) servicing the DF RANCH 22-24 (05-123-30024) is now out of service as per rule 1102.O.(2). The most recent successful pressure test was conducted 11/16/2020.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461527 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 410150 Location Type: Well Site ☐
Name: DF RANCH-611N61W Number: 22SESW
County: WELD No Location ID
Qtr Qtr: SESW Section: 22 Township: 11N Range: 61W Meridian: 6
Latitude: 40.901440 Longitude: -104.194160

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 09/17/2009
Maximum Anticipated Operating Pressure (PSI): 62 Testing PSI: 62
Test Date: 09/18/2018

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date:

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 filed to report STATUS CHANGE notification. The following flowline(s) are now out of service:
12330024FL: services the DF RANCH 22-24 (05-123-30024)
All other flowlines will remain as previously reported.
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 10/11/2023 Email: flowlines@civiresources.com

Print Name: Stephany Olsen

Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____



Director of COGCC

Date: 11/8/2023

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

403558056	OFF-LOCATION FLOWLINE GIS SHP
-----------	-------------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)