

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2023

Submitted Date:

10/27/2023

Document Number:

694100203**FIELD INSPECTION FORM**Loc ID 318801 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Kuhn, Denny		cogcc@kpk.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 318801 UPRR 43 Pan Am I-61 and associated I-27 flowline. Any corrective actions from previous inspections that have not been addressed are still applicable. There were operator personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

Comment: [Statewide unnecessary equipment, weeds, waste, and trash requirements](#)Corrective Action: [Comply with Rule 606](#)Date: [11/10/2023](#)Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: [No spills at time of inspection.](#)☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

KPK personnel were on location at time of inspection. Some were cutting trench of the removed flowline and another was collecting soil samples. Three soil samples were collected along the open flowline trench, another 5 were taken at the open wellhead excavation. The open excavation is approximately 20ft x 15ft x 8ft deep. Samples were taken at the base and all four side walls. Northern most section (approx. 30ft) of the trench was ultimately backfilled. The rest has construction fence on both sides.

robinsotl

10/27/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403581673	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306850
694100204	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6306841