

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2023

Submitted Date:

11/02/2023

Document Number:

701103842

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 83130
 Name of Operator: STRACHAN EXPLORATION INC
 Address: 383 INVERNESS PKWY, STE 360
 City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|----------------|-------------------------------|---------|
| Strachan, Steve | (303) 785-7006 | sms@strachanexploration.com | |
| Welsh, Brian | | brian.welsh@state.co.us | |
| Sanchez, Chris | | chris.sanchez@state.co.us | |
| Wheeler, Steven | | steven.wheeler@state.co.us | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Quint, Craig | | craig.quint@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|-----------------|--------|-------------|------------|---------|------------------------------|-------------|
| 470774 | Flowline System | AC | 01/09/2020 | | - | McClave Gas Gathering System | EG |

General Comment:

[Flowline integrity inspection](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--------------------------------------|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | No volume on capacity label. | | |
| Corrective Action: | Mark tank with tank capacity volume. | Date: | 11/30/2023 |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|----------------------|
| Comment: | <input type="text"/> | Date: | <input type="text"/> |
| Corrective Action: | <input type="text"/> | | |

Good Housekeeping:

| | | | |
|--------------------|-------------------------------|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment on location. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 11/30/2023 |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|--------------------|--|--------|--|-------|------------|
| | | | | | |
| Comment: | Stained ground at compressor. | | | | |
| Corrective Action: | In accordance with Rule 912.a.(2) Operator will investigate, cleanup, and document impacts resulting from Spill and Releases as soon as the impacts are discovered. Contact the area Environmental Protection Specialist Chris Sanchez | | | Date: | 11/03/2023 |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | | corrective date |
|--------------------|-----|-------|-----------------|
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Compressor | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | | STEEL AST | | 37.852138,-102.469482 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |
| Other (Capacity) | <input type="text"/> |

| | | | | |
|--|----------|---------------------|---------------------|-------------------------|
| Other (Type) _____ | | | | |
| Berms | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | | | | Inadequate |
| Comment: Unmaintained tank berm. | | | | |
| Corrective Action: Maintain tank berm. | | | | Date: <u>11/30/2023</u> |
| Venting: | | | | |
| Yes/No | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Flaring: | | | | |
| Type | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Inspected Facilities

Facility ID: 470774 Type: Flowline API Number: - Status: AC Insp. Status: EG

Flowline

| #1 | Type: | of Lines |
|----|-------|----------|
|----|-------|----------|

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Unregistered facility with a compressor at 37.852036 -102.469329 north west of the Daniels 1-27 well api# 05-099-06349.

Corrective Action: Register facility in a Form 12.

Date: 11/30/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 403581960 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307135 |
| 701103845 | Unregistered compressor station circled in red | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307128 |
| 701103846 | Unregistered compressor station Google Maps | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307129 |
| 701103848 | Flowline integrity inspection 701103842 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6307130 |