

Inspection Photos
Location: Becks 41-16 and Becks 41-16 TR
Facility ID: 334237





Photo 1 – Well Site Placard, Incorrect Latitude and Longitude

Photo 2 – Well Site Placard, Incorrect Longitude

Inspection Photos
Location: Becks 41-16 and Becks 41-16 TR
Facility ID: 334237



Photo 3 – TR wellhead

Photo 4 – Wellhead

Inspection Photos
Location: Becks 41-16 and Becks 41-16 TR
Facility ID: 334237



Photo 5 – Pit looking east

Photo 6 – Pit Freeboard

Inspection Photos
Location: Becks 41-16 and Becks 41-16 TR
Facility ID: 334237



Photo 7 – Vegetation Around equipment

Photo 8 – Plugged culvert in cross drainage, erosion on downstream side of roadway at this location

Inspection Photos
Location: Becks 41-16 and Becks 41-16 TR
Facility ID: 334237



Photo 9 – Riling along access road