

Inspection Photos

Loc: 322234

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 11/08/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road. There is erosion occurring along the road.



Inspection Photos



Photo 2. Facing southeast along the road. There are undesirable weeds growing along the road side that need to be removed/controlled..



Inspection Photos



Photo 3. Facing south toward the location. The well has been plugged and abandoned however final reclamation has not yet been completed.



Inspection Photos



Photo 4. Facing southwest along the fill slope. The location will need to be recontoured back to the original slopes



Inspection Photos



Photo 5. The electric utilities remain at the location and should have been removed with 3 months of abandonment. The entire powerline and poles servicing this location must be removed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 11/08/2023

Inspection Photos



Photo 6. Facing toward the south side of the location. There are tanks that have not been removed. All equipment should have been removed within 3 months of abandonment..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 11/08/2023

Inspection Photos



Photo 7. Facing west at the south side of the location. There is an erosion channel shown at red arrow which will need to be repaired and stabilized.



Inspection Photos



Photo 8. Facing southeast at the south side of the location. There is an erosion channel shown at red arrow which will need to be repaired and stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322234 | Date: 11/08/2023

Inspection Photos



Photo 9. Facing east along the cut slope. There is rilling erosion along the cut slope.



Inspection Photos



Photo 10. Facing east along the cut slope. There is rilling erosion along the cut slope.



Inspection Photos



Photo 11. Facing south at the location. All gravel must be removed and the location will must be reclaimed per 1004 Rules.

