

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2023

Submitted Date:

11/09/2023

Document Number:

713600361

FIELD INSPECTION FORM

 Loc ID 321069 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 76859
 Name of Operator: SCHREIDER & COMPANY INC
 Address: 8200 S QUEBEC ST SUITE A3-768
 City: CENTENNIAL State: CO Zip: 80112
Findings:

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	
SCHREIDER JR RUDY		schreiderco@outlook.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
321069	LOCATION	AC			-	STATE-631S41W 17NWSE	RI

General Comment:

On 10/31/2023, Ryan Costa conducted a location inspection at the State 1-17 and Hume 1-20 facility.
See attached photos and additional details within this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	There are weeds and dry vegetation debris around the equipment which is a fire hazard. The weeds around the location need to be controlled and debris removed. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606.	Date:	10/31/2023
Type	OTHER		
Comment:	There is a pipe riser at the wellhead with no OOSLAT. Corrective action will remain out of compliance until completed.		
Corrective Action:	Comply with Rule 606. Remove all unused equipment. Remove pipe riser or LOTO.	Date:	10/31/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	There is no netting at the open top tank located at the offsite facility Lat/Long:37.33139, -102.06825. Corrective action will remain out of compliance until completed.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 10/31/2023

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	There is a vertical separator with no secondary containment. There is also no secondary containment at the offsite facility located at Lat/Long:37.33139, -102.06825. Corrective action will remain out of compliance until completed.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date: 10/31/2023

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 321069 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: There is an offsite facility located Lat/Long:37.33139, -102.06825. It appears to be an active facility however there are no registered flowlines. There is a sign for Shrieder & Company and Dover Atwood at this facility with the name Hume 1-20.

Corrective Action: Submit an eForm 44 Flowline Report per Rule 1101.a. Contact ECMC Area Integrity Engineer.

Date: 10/31/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600365	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317225