

Inspection Photos

11/06/2023

Operator: LARAMIE ENERGY LLC #10433

Location ID: 481743

Inspection Doc: 696205412

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 1: Photos 1-2 taken from the southeast end of the working pad surface. Photos provide an overview of the Location from southwest, west north to northeast



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 3: Photos taken from the southeastern perimeter of the Location. The two sediment traps per the 2A have been constructed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



November 6, 2023



November 6, 2023

Photo 4: Photos taken from the topsoil stockpiles on the eastern perimeter of the Location. Photo shows hydromulch applied to areas of the stockpiles (adjacent to the sediment traps recently implemented) is no longer in proper functioning condition



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 5: See comments under photo 4.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 6: Photos taken from the slope drain on the northwest end of the Location; outlet protection remains missing per good engineering practices.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 7: Photo taken from the slope drain on the west end of the Location; outlet protection remains missing per good engineering practices.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



November 6, 2023



November 6, 2023

Photo 8: Photos taken from the western perimeter of the Location. Sediment trap per the 2A has been constructed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 9: Hydromulch along the western topsoil stockpiles have been maintained; control appeared to be in proper functioning condition at time of inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 481743



Photo 10: Photo shows weeds observed along the topsoil stockpiles. Weed management activities appear to have been performed, and the majority of Noxious weeds previously observed on the topsoil stockpiles have been removed. It is unclear if plants had been managed prior to maturity, and some weeds with seed were observed along areas of the topsoil stockpile on the north side of the Location. Weed management at this time is considered “in-process”; additional weed management efforts will likely be necessary during the 2024 growing season to comport with 606.c and 1003.f requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources