

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**




Debris around wellhead



Debris around wellhead

Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060



Debris around wellhead



Illegible and missing required information

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Debris where production equipment was removed



Debris where production equipment was removed

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Debris where production equipment was removed



Debris where production equipment was removed

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Debris where tank battery was removed



Erosion along edge of location

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Location from Southwest corner



Location from Northwest corner

**Crowheart Energy LLC
Peppler Fee Com 12-18
Location ID: 313060**



Location from Northeast corner



Location from Southeast corner