

Interim Reclamation and Stormwater Inspection

Date: 11/02/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 417324

Inspection Document #: 708200680

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Photo 1. Stained soil observed on the south end of the tank battery facility.

Inspection Photos
Location Name: State 16-11-9-60H
Location ID: 417324



Photo 2. Unused equipment within the secondary containment of the tank battery.

Inspection Photos
Location Name: State 16-11-9-60H
Location ID: 417324



Photo 3. Trash observed in the eastern side of the interim areas.

Inspection Photos
Location Name: State 16-11-9-60H
Location ID: 417324



Photo 4. Previous inspection documented string/twine; this has not been removed since the previous corrective action inspection has been submitted.



Photo 5. Trash and undesirable vegetation (e.g russian thistle, kochia, and crested wheatgrass) observed throughout the eastern interim areas.



Photo 6. The eastern interim areas have been recently mowed, though there appears to be evidence of crested wheatgrass, an introduced species.



Photo 7. Non-uniform vegetative cover resulting in bare/exposed soils within the reclaimed pit. Undesirable vegetation (e.g. russian thistle, kochia and crested wheatgrass) observed throughout. Additional reclamation activities are required.

Inspection Photos
Location Name: State 16-11-9-60H
Location ID: 417324



Photo 8. Continued from the previous photo, facing towards the southeast corner of the reclaimed pit.



Photo 9. Continued from Photos 7 & 8. Southern portion of the former pit area.