

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2023

Submitted Date:

11/09/2023

Document Number:

713300283**FIELD INSPECTION FORM**Loc ID 321296 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Civitas		Inspections@civiresources.com	
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206610	WELL	SI	05/01/2022	GW	013-06105	OGREN H. UNIT 1	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	production water tank volume, faded, unreadable		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	12/09/2023
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	metal tube panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation panels		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	shared with condensate tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 206610 Type: WELL API Number: 013-06105 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: EQUIPMENT ONSITE

Comment: well and flowline appeared to be shut in, defined inactive 4-30-2022, Form 6a 1-24-2023

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/08/2022

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type:

End Surf Csg Pressure: 0

Comment: submit report

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Thursday 11-9-2023 at approximately 12:00 I, Inspector Michael Kester, conducted an on-site inspection.</p> <p>Location: Ogren H unit 1</p> <p>Operator: Crestone Peak</p> <p>API#: 013-06105</p> <p>County: Boulder</p> <p>While there, I observed well site with production site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign, tank volume, Rule 605h, corrective action date 12-9-2023, photo 6</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the ECMC</p> <p>This is a continuing education inspection</p>	kesterm	11/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300284	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6317900