

**Inspection Photos**  
**Location Name: HOWARD USX A/09-19**  
**Location #: 423200**



**Photo #1**

**Howard USX A 09-06D (123-33532) Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Workover: Tag cement; Cut tubing**



**Photo #2**

**Howard USX A 09-06D Wellsite**  
**Plugged & Abandoned | PA**  
**Plugging Ops; Workover: Tag cement; Cut tubing**  
*Site safety signage*



**Inspection Photos**  
**Location Name: HOWARD USX A/09-19**  
**Location #: 423200**




**Photo #3**

**Howard USX A 09-06D Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Workover: Tag cement; Cut tubing**

*Wellsite entrance*



**Photo #4**

**Howard USX A 09-06D Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Workover: Tag cement; Cut tubing**

*JSA: 2023-11-07*



**Inspection Photos**  
**Location Name: HOWARD USX A/09-19**  
**Location #: 423200**



**Photo 5**

**Howard USX A 09-06D Wellsite**

**Plugged & Abandoned | PA**

**Plugging Ops; Workover: Tag cement; Cut tubing**

Wellsite sign

*prior photo*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources