

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2023

Submitted Date:

11/10/2023

Document Number:

708902177

**FIELD INSPECTION FORM**Loc ID 334799 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	
, Engineering		dnr_cogccengineering@state. co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211580	WELL	PR	06/01/2021	GW	045-07341	COUEY 8-3 (C8E)	PR
258069	WELL	PR	06/01/2021	GW	045-07618	COUEY 8-3A (C8E)	PR

**General Comment:****CECMC Inspection Report Summary**

On 11/07/2023 at approximately 09:50 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at CAERUS PICEANCE LLC COUEY 8-3 (C8E) pad.

Location # 334799 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas &amp; within close proximity to NSO Habitat area.

Location is approximately 207 yards from West Mamm Creek &amp; 312 yards from Middle Mamm Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - COUEY 8-3 bradenhead connected to flowline/No FORM 4 SUNDRY with a CA date of 10/17/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/970-285-2615		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels		

Corrective Action:				Date:	
<b>Equipment:</b>				corrective date	
Type: Gas Meter Run		# 2			
Comment:					
Corrective Action:		Date:			
Type: Bird Protectors		# 2			
Comment:					
Corrective Action:		Date:			
Type: Bradenhead		# 1			
Comment:		<p>COUEY 8-3 bradenhead line is connected to flow line.</p> <p>Please refer to FORM 4 SUNDRY document #'s 403189246 &amp; 403453629. Operator proposed &amp; was approved to install a pressure transducer for continuous pressure monitoring as part of a Pressure Management Plan for the COUEY 8-3 well bradenhead.</p> <p>Operator has also connected bradenhead to flow line &amp; there's no check valve. This work was neither proposed or approved in any FORM 4 SUNDRY.</p>			
Corrective Action:		Contact CECMC Engineering group & discuss observed compliance issue.		Date: 11/17/2023	
Type: Horizontal Heated Separator		# 2			
Comment:					
Corrective Action:		Date:			
Type: Deadman # & Marked		# 2			
Comment:		Marked			
Corrective Action:		Date:			
Type: Gas Meter Run		# 1			
Comment:		Summit Midstream			
Corrective Action:		Date:			
Type: Bradenhead		# 2			
Comment:		Pressure transducers located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:		Date:			
Type: Plunger Lift		# 2			
Comment:		All wells on plunger lift			
Corrective Action:		Date:			
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			
<b>Paint</b>					
Condition	Adequate				
Other (Content)					

Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment: <a href="#">Unlined containment</a>					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	211580	Type:	WELL	API Number:	045-07341	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	258069	Type:	WELL	API Number:	045-07618	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse
Compaction						Small areas of light compaction
		Compaction				
		Culverts				
		Ditches				
		Gravel				Sparse

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Equipment for observed compliance issue.	smelserw	11/10/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902178	Inspection 708902177 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318629</a>
708902179	Inspection 708902177 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318630">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6318630</a>