

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5580 From entrance to location




Photo # 5581 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5582 Location



Photo # 5583 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5584 Location



Photo # 5585 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5586 Location



Photo # 5587 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5588 Location




Photo # 5589 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5590 Location



Photo # 5591 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5592 Location



Photo # 5593 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5594 Tank label contains inaccurate information



Photo # 5595 44A-08-07-95 Wellhead cellar lacks wildlife egress & cellar cover improperly placed & only partially covering cellar

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5596 Multiple cellar covers improperly placed & only partially covering wellhead cellars



Photo # 5597 Unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5598 PRV lacks vent line



Photo # 5599 PRV lacks vent line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5600 PRV vent line lacks cap



Photo # 5601 PRV vent line lacks cap

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832



Photo # 5602 Rupture disc vent line lacks cap



Photo # 5603 PRV vent line lacks cap



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MONUMENT RIDGE B Pad

Location ID: 442832




Photo # 5604 PRV vent line lacks cap