

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Nov 8, 2023 at 1:29:52 PM
CO



Nov 8, 2023 at 1:29:58 PM
CO

Photo # 6011 From entrance to location

Photo # 6012 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 6013 Location

Photo # 6014 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 6015 Location



Photo # 6016 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572



Photo # 6019 Location



Photo # 6020 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 341-15 Pad

Location # 335572




Photo # 6021 RWF 332-15 & 432-15 separators have PRV & rupture disc vent lines that terminate in an unsafe manner




Photo # 6022 RWF 332-15 & 432-15 separators have PRV & rupture disc vent lines that terminate in an unsafe manner