

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2023

Submitted Date:

11/11/2023

Document Number:

708902200

**FIELD INSPECTION FORM**Loc ID 334688 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

23 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269780	WELL	SI	07/01/2022	GW	045-09409	RULISON FEDERAL 11-14	SI
274573	WELL	SI	07/01/2022	GW	045-13361	FEDERAL 11-2 (RA11)	SI
274585	WELL	SI	07/01/2022	GW	045-13366	FEDERAL 11-8 (RA11)	SI
274586	WELL	SI	07/01/2022	GW	045-13365	FEDERAL 11-7 (RA11)	SI
292227	WELL	SI	07/01/2022	GW	045-14648	FEDERAL 11-1D (RA11)	SI
292228	WELL	SI	07/01/2022	GW	045-14647	FEDERAL 11-7A(RA11)	SI

**General Comment:****CECMC Inspection Report Summary**

On 11/09/2023 at approximately 12:26 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC RULISON FEDERAL 11-14 (RA11) Pad.

Location # 334688 in Garfield County Colorado.

Please refer to inspection 708901828 conducted on 09/29/2023, previous corrective actions have been completed.

Location is within Black Bear/High Priority/Density Habitat areas.

While there, I observed normal production operations.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Jersey barriers		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Orange plastic safety barrier fence & hog panels around holes behind separator units		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Pressure transducers located on all bradenhead, all bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	Summit Midstream		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient				
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:						
Date:						

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 269780 Type: WELL API Number: 045-09409 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut InLast produced August 2023

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 274573 Type: WELL API Number: 045-13361 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut InLast produced August 2023

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 274585 Type: WELL API Number: 045-13366 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut InLast produced August 2023

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 274586 Type: WELL API Number: 045-13365 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut InLast produced August 2023

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 292227 Type: WELL API Number: 045-14648 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut InLast produced August 2023

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 292228 Type: WELL API Number: 045-14647 Status: SI Insp. Status: SI

<b>Idle Well</b>	
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned	Reminder: _____
<u>Comment:</u> <div>Shut In Last produced August 2023</div>	
Corrective Action: <div></div>	Date: _____

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse in sections
Gravel						Sparse in some areas
		Culverts				
		Ditches				
Compaction						Light compaction in some areas
Berms						
		Compaction				Light compaction in some sections
Ditches						
Rip Rap						
Retention Ponds						

Comment: Location appears to have some gravel throughout the location with light compaction. Places with sparse to no gravel are present on location. Sparse gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708902201	Inspection 708902200 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6319049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6319049</a>
708902202	Inspection 708902200 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6319050">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6319050</a>