

Inspection Photos

Loc: 429093

Operator: **AUSCO PETROLEUM INC**

Inspection Date: 11/08/2023

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the location. The blue frac tank which appears to be unused, does not have secondary containment and needs to be removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:429093 | Date: 11/08/2023

Inspection Photos



Photo 2. There are 2 orange buckets that appear to have oil with no labeling and no containment. Previous corrective action was not completed.



Inspection Photos



Photo 3. There is oil stained soil at base of pump jack. There is a blue chemical jug not properly stored in containment.



Inspection Photos



Photo 4. There is an unknown barrel with no labeling or containment. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:429093 | Date: 11/08/2023

Inspection Photos



Photo 5. There is no wildlife protection at the wellhead.



Inspection Photos



Photo 6. The other wellhead on location does have wildlife protection.



Inspection Photos



Photo 7. Facing southwest toward the bitcoin equipment which is not in operation.



Inspection Photos



Photo 8. There is a portable secondary containment installed for the 2 chemical totes.



Inspection Photos



Photo 9. It appears in between the equipment there is darkened gravel from a possibly leak which has not been cleaned up. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:429093 | Date: 11/08/2023

Inspection Photos



Photo 10. The plastic liner has become folded over needs to be repaired. Liner should be properly staked down.



Inspection Photos



Photo 11. Facing north toward the bitcoin equipment. There are multiple tanks and secondary containment is not sufficient or maintained to contain a spill.



Inspection Photos



Photo 12. Facing south at the location. All gravel must be removed and the location will must be reclaimed per 1004 Rules.



Inspection Photos



Photo 13. Facing south at the location. All gravel must be removed and the location will must be reclaimed per 1004 Rules.



Inspection Photos



Photo 14. Facing south at the location. All gravel must be removed and the location will must be reclaimed per 1004 Rules.



Inspection Photos



Photo 15. South side of the location facing north. The old wattles in this area needs to be replaced or removed. Previous corrective action was not completed.



Inspection Photos



Photo 16. Facing south at the perimeter ditch. The check dams have filled in with sediment and need to be cleaned out. Previous corrective action was not completed.



Inspection Photos



Photo 17. Facing south at the location. All gravel must be removed and the location will must be reclaimed per 1004 Rules.



Inspection Photos



Photo 18. The wattles along the west perimeter of the location are degraded and need to be replaced or removed.



Inspection Photos



Photo 19. Facing southwest toward the location.



Inspection Photos



Photo 20. There is a dripping leak at the backside of the tank. Operator was immediately notified.



Inspection Photos



Photo 21. There is a dripping leak at the backside of the tank. Operator was immediately notified.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:429093 | Date: 11/08/2023