

Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 11/8/2023



Inspection Photos



Photo 1. Facing north along the former access road. There is erosion along the road that must be repaired.



Inspection Photos



Photo 2. Facing southwest toward the access road which must be reclaimed. There is erosion occurring along this area that needs to be repaired and stabilized.



Inspection Photos



Photo 3. Facing east toward the abandoned wellsite which was never reclaimed. Soils remain bare of vegetation and there is erosion occurring. There is various debris throughout the location and stained soils.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 043-40000 | Date: 11/8/2023

Inspection Photos



Photo 4. Facing south at the location. There is various debris and stained soils throughout the location.



Inspection Photos



Photo 5. Facing southeast. There is a degraded perimeter fence that remains around the location. There is also an old bridge timber that remains.



Inspection Photos



Photo 6. Facing southwest at the location. There is various debris throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Facing northwest at the wellsite. There is an abandoned powerpole that has not been removed

